

Project Type:

UNDERWATER INSPECTION
SUPERVISION

Vessel(s):

Terra Nova FPSO

Client:

Spectrol Group
St. John's, NL



Profile:

Poseidon Marine Consultants Ltd. revised work packages and supervised the annual underwater inspection of the Terra Nova FPSO during the summers of 2008 and 2009.



Project Type:

ENVIRONMENTAL RESPONSE
SUPERVISION

Vessel(s):

Terra Nova FPSO

Client:

GARD A/S

Profile:

Poseidon Marine Consultants Ltd. attended the Terra Nova oil field to observe and comment on efforts to evaluate and clean the underwater hull of the *Terra Nova FPSO*, subsequent to an oily water discharge incident which occurred the previous year. This CNLOPB-approved exercise consisted of two primary components. The first involved collection of growth, oil and water samples from locations along the underwater portion of the hull. The second involved scraping of the hull, using a fabricated tool attached to an ROV.

Upon the conclusion of this exercise, **Poseidon Marine Consultants Ltd.** compiled on behalf of the subject client a report outlining the following:

- *sequence of events and procedures followed*
- *overall results of cleaning efforts*
- *difficulties and challenges encountered in the process*
- *commentary regarding the improvement of future cleaning exercises*